

Month	Reference list	Country	Plant
May 2021	Reverse engineering of gearset Compressor Atlas Copco GT050N4K1/GT040N2K2	France	Chemical
May 2021	Troubleshooting pulsation hydraulic system during start-up Steam Turbine Acec M2209.S 6,2 MW	Sweden	Chemical
May 2021	Inspection of Steam Turbine ABB AEG Kanis G20 9,445 MW	Belgium	Paper & Pulp
May 2021	Alignment , boroscope inspection of Steam Turbine Man Marc 2 B00 8,5 MW - Cincinnati RTP 56II	Spain	Paper & Pulp
May 2021	Boroscope turbine & gearbox inspection Steam Turbine Siemens SST-600 24,77mW	Sweden	Paper & Pulp
May 2021	NSC Steam Turbine Man Marc 2-C10 5,72 MW	Belgium	Biomass Energy
May 2021	Reverse Engineering fan KCB Nir 60-40 PKD-DT/VL-VE0009/(010)	Belgium	Nuclear
May 2021	Inspection of actuators Steam Turbine Siemens SST NG50/40-3	Spain	Paper & Pulp
May 2021	Overhaul of 2 governors EG10-P Steam Turbine ACEC M2209.S 6,2 MW	Sweden	Chemical
April 2021	Major overhaul of Steam Turbine ACEC M2209.S 6,2 MW	Sweden	Chemical
April 2021	Inspection and repair of bearings PWG Turboblower GX420 Air	Greece	Waste Water
April 2021	Delivery of spare parts Steam Turbine Siemens SST-600 24,77 MW	Sweden	Power
April 2021	Rotor replacement and assembly of Compressor FCM Bell E12K	Switzerland	Salt
April 2021	Delivery of superbolts M48 Compressor Man Nox R56-4N	Belgium	Chemical
April 2021	Major overhaul of Steam Turbine AEG Kanis GE20 2MW	Switzerland	Waste
March 2021	Revision set of thrustpads Steam Turbine Man MARC 2 H01 8MW	Belgium	Biomass Energy
March 2021	Major overhaul of Compressor unit BLNC LP/HP Siemens Demag VK 40	Germany	Air Separation
March 2021	Repair of tilting pad & bull gear bearings N2 Integral Geared Compressor Joy TA24M4CRZ/30	Germany	Air Separation
March 2021	Delivery of spare parts N2 Integral Geared Compressor Joy TA24M4CRZ/30	Germany	Air Separation
March 2021	Repair of oilpump Feed water Turbine KKK CF5GS 1,3 MW	Sweden	Paper & Pulp
March 2021	Delivery of new HP pump Steam Turbine Man Marc 2-B00 8,5 MW	Spain	Paper & Pulp
March 2021	Repair of cooler pump Steam Turbine Man Marc 2-B00 8,5 MW	Spain	Paper & Pulp
March 2021	Manufacturing, delivery and installment of parts GHH Feedgas & Recycle Compressor FGR 11,5 MW	Germany	Air Separation
March 2021	Repair of bearings Steam Turbine ABB Stal VAX HP 25 29,2MW	Sweden	Paper & Pulp
March 2021	Delivery of spare parts Steam Turbine ABB Stal VAX HP 25 29,2MW	Sweden	Paper & Pulp
March 2021	NSC Steam Turbine ABB Stal VAX HP 25 29,2MW	Sweden	Paper & Pulp
March 2021	Repair of radial bearings Steam Turbine MAN MAA10/MAC 10 8,2MW	Spain	Power
March 2021	Major overhaul and repair of Demag Compressor AR250-7-2	Germany	Air Separation
February 2021	High speed balancing of rotors pinions Nitrogen Compressor Atlas Copco GT050 N4K1	France	Air Separation
February 2021	Reverse Engineering and delivery of coupling Steam Turbine Siemens SST NG 50/40-3 25,0MW	Spain	Paper & Pulp
January 2021	Inspection and repair of Nitrogen Recycle Compressor Joy 2X2 MSG-10RC/1500	Germany	Air Separation
January 2021	Major overhaul Steam Turbine Stal Laval DDSM2070 15 MW	France	Paper & Pulp

December 2020	Repair of bearings gearbox Steam Turbine Siemens SST NG 50/40-3 25,0MW	Spain	Paper & Pulp
December 2020	Repair of rotor Steam Turbine ACEC M2209.S 6,2 MW	Sweden	Chemical
December 2020	Reverse Engineering & Manufacturing of Bullgear bearing Nitrogen Recycle Compressor Joy 2X2 MSG-10RC/1500	Germany	Air Separation
December 2020	Minor overhaul and turbine casing repair of Steam Turbine AEG Kanis GE20 2 MW	Sweden	Waste
December 2020	Manufacturing and delivery of spare parts Compressor CO1 Alstohm Rateau TSD65/65 SXA	Switzerland	Air Separation
December 2020	Overhaul of Compressor Sulzer Escher Wyss 64/5, Gearbox Maag GN19, Steam Turbine Sulzer Escher Wyss NGN560	France	Chemical
November 2020	Major overhaul of Steam Turbine Siemens SST NG50/40-3 25MW	Spain	Paper & Pulp
November 2020	Repair of axial bearing gearbox/turbine Steam Turbine MAN MAA10/MAC 10 8,2 MW	Spain	Power
November 2020	Reverse Engineering and Delivery of 3 D models parts Air Compressor Demag CVK 32-3	Italy	Air Separation
November 2020	Inspection of Centrifugal Compressor Demag VK90	France	Air separation
November 2020	Inspection of Air Compressor Demag CVK 32-3	Italy	Air separation
October 2020	Inspection and installment of the stuffingboxes Compressor Escher Wyss 90/4a EJ	Switzerland	Salt
October 2020	Manufacturing and delivery of new rotor CO2 Compressor FCM Bell E12K	Switzerland	Salt
October 2020	Reverse engineering & Manufacturing and delivery of Capital Spare parts Nitrogen Compressor GT050 N4K1	France	Air separation
October 2020	Cleaning of the steambox and replacement of the carbon rings Steam Turbine SST-060 AFA 46 GTS Twin	Spain	Paper & Pulp
October 2020	Delivery of clutch turning gear Steam Turbine ABB Stal Vax HP25 29,2 MW	Sweden	Paper & Pulp
October 2020	Major overhaul of Steam Turbine Siemens SST-600 24,77 MW	Sweden	Power
October 2020	Manufacturing and delivery of complete stuffingbox Compressor Escher Wyss 90/4a EJ	Switzerland	Salt
September 2020	Shaft and bearing repair generator + start-up of Steam Turbine MAN Turbo MARC 2-H02 8,73 MW	Sweden	Power
September 2020	Replacement of 2 oil pumps Steam Turbine Man Marc 2-B00 8,5 MW	Spain	Paper & Pulp
September 2020	Inspection of Air Compressor Atlas Copco H2H8-4 SP 1480 KW	Belgium	Chemical
September 2020	Inspection of Steam Turbine KKK Twin - CA 56 5,385 MW	Belgium	Waste
September 2020	Minor overhaul of Steam Turbine MAN Marc 2 H01 8 MW	Belgium	Biomass Energy
September 2020	Major overhaul of Steam Turbine BRNO-CSFR R14-A0 14 MW	Sweden	Power
September 2020	Manufacturing and delivery of spare parts Steam Turbine ABB Stal Vax HP25 29,2 MW	Sweden	Paper & Pulp
September 2020	Minor overhaul of Steam Turbine ABB Stal Vax HP25 29,2 MW	Sweden	Paper & Pulp
September 2020	EMD and visual inspection of generator Steam Turbine Siemens SST-110 Twin AFA 46GT6 4,106 MW	Sweden	Paper & Pulp
September 2020	Inspection of Steam Turbine Siemens SST-110 Twin AFA 46GT6 4,106 MW	Sweden	Paper & Pulp
September 2020	Minor overhaul of Steam Turbine Triventi TST-1060-EB-039 3,896 MW	Sweden	Power
August 2020	Inspection of Steam Turbine Fincantieri 36 CE 7,28 MW	Sweden	Power
August 2020	Overhaul of 2 governors Steam Turbine Acec M2209.S 6,2 MW	Sweden	Chemical
August 2020	Reverse Engineering of Cranckcase H2 Compressor Sulzer C2C11CP	France	Chemical
August 2020	Inspection Steam Turbine Siemens SST 110 3MW	Sweden	Power
August 2020	NSC Steam Turbine Siemens SST 110 3MW	Sweden	Power
August 2020	Overhaul Steam Turbine MAN MAA10/MAC10 8,2 MW	Spain	Power
August 2020	Minor inspection Steam Turbine MAN Marc 2 C10 5,72MW	Belgium	Biomass Energy
August 2020	Repair actuators Steam Turbine Siemens T8440	The Netherlands	Waste
August 2020	Inspection & repair bearings of Feedgas & Recycle Compressor GHH FGR 11,5 MW	Germany	Air separation

July 2020	Overhaul of N2 Integral geared Compressor Joy TA26M4 CRZ/30	Germany	Air separation
June 2020	Repair IGV of N2 Integral geared Compressor Joy TA26M4 CRZ/30	Germany	Air separation
June 2020	Reverse Engineering of gearset & manufacturing bull gear for Main Air Compressor Joy	Germany	Air separation
June 2020	Troubleshooting Steam Turbine Acec M2209.S 6,2 MW	Sweden	Chemical
June 2020	Inspection and repair of cylinder and piston Steam Turbine Acec M2209.S 6,2 MW	Sweden	Chemical
June 2020	Major overhaul Steam turbine KKK CF5GS 1,2 MW	Sweden	Paper & Pulp
June 2020	Delivery & installment of servomotor, check up of control valves and adjustment of axial probes Steam Turbine B+V Marc 2-C01 7,795 MW	Sweden	Waste
June 2020	Inspection and repair set of bearings Turbine Compressor Escher Wyss 90/4a EK and 90/4aEJ	Switzerland	Salt
May 2020	Troubleshooting/Inspection and repair of Feedgas & Recycle Compressor GHH FGR 11,5 MW	Germany	air separation
May 2020	Troubleshooting Steam Turbine KKK Twin CA56 5,385 MW	Belgium	Waste
May 2020	Inspection and repair gearbox Steam Turbine Man Turbo Marc 2-H02 8,7 MW	Sweden	Power
April 2020	Engineering & Visualisation Rotor Dynamics Compressor V450	Belgium	Chemical
April 2020	Inspection of bearings Compressor Rateau CM2.80.3	France	Chemical
April 2020	Repair of turbine casing and rotor Steam Turbine Man Turbo Marc 2 - H02 8730 KW	Sweden	Power
April 2020	Major overhaul of Compressor GHH FGR	Germany	Chemical
March 2020	Engineering & Visualisation Rotor Dynamics Compressor V860.90	Belgium	Chemical
March 2020	Inspection and repair of CRF regulating and stop valve Steam Turbine Siemens KKK Twin AFA 46GTS 600 KW	Belgium	Chemical
March 2020	Inspection of Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	The Netherlands	Food
March 2020	NSC of Steam Turbine B+V Marc 2 - C01 7,795 MW	Sweden	Waste
March 2020	NSC of Steam Turbine AEG Kanis GE 20 2 MW	Sweden	Waste
March 2020	NSC of Steam Turbine MAN Marc 4 20MW	Spain	Biomass Energy
March 2020	NSC of Steam Turbine Triveni STST-1060-EB-39 4MW	Sweden	Power
March 2020	Major overhaul of Steam Turbine KKK CF5 GS 1,3 MW	Sweden	Paper & Pulp
March 2020	Inspection of Compressor MAN NOX V20	Belgium	Chemical
March 2020	Major overhaul of Compressor Atlas Copco GT021T3 DO/021 T1DO	Germany	Chemical
March 2020	Troubleshooting control valve Steam Turbine Siemens SST 110 4MW	Sweden	Paper & Pulp
February 2020	Repair of compressor Escher Wyss 90/4a EK	Switzerland	Salt
February 2020	Manufacturing and delivery of spare parts Compressor Sulzer Escher Wyss 90/4a EJ	Switzerland	Salt
February 2020	Troubleshooting Steam Turbine BBC DEF Zi44 26,8 MW	The Netherlands	Waste
February 2020	Delivery of Revak series 2 Lubrication oil pump	The Netherlands	Refinery
January 2020	NSC of 2 x feed water turbines KKK CF5GS 1,3 KW	Sweden	Paper & Pulp
January 2020	Repair of bearings Compressor BHS Cincinnati C202	Italy	Chemical
January 2020	Delivery of spare parts valve HP side Steam Turbine KKK AFA GT44 GTA 2,3 MW	Sweden	Paper & Pulp
January 2020	Inspection and repair of Valves HP side Steam Turbine KKK AFA GT44 GTA 2,3 MW	Sweden	Paper & Pulp
January 2020	Manufacturing and delivery of spare parts Steam Turbine ABB ACEC M2209.S 6,2 MW	Sweden	Chemical
January 2020	Inspection of control valve Steam Turbine ABB ACEC M2209.S 6,2 MW	Sweden	Chemical
January 2020	Revision of Steam Turbine KKK CFR3/AFA6 2,64 MW	Germany	Chemical
January 2020	Revision Compressor Escher Wyss 90/4a EJ	Switzerland	Salt

January 2020	Troubleshooting control system and inspection of 2 stop valves Steam Turbine Siemens 1DT 448-7DE02-Z 22,465 MW	Spain	Power
December 2019	Troubleshooting Steam Turbine Man Marc 2 8 MW	Belgium	Biomass Energy
December 2019	Manufacturing and delivery of spare part Steam Turbines Stal Laval DDM2070 30 MW and DCDUM2070 22,45 MW	Sweden	Paper & Pulp
December 2019	Manufacturing and delivery of spare parts Compressor Sulzer Escher Wyss RT28 ER80340	Switzerland	Salt
November 2019	Inspection of Steam Turbine KKK Twin - CA 56 5,385 MW	Belgium	Waste
November 2019	NSC of Steam Turbine Dresser Rand SST503-H 1,9 MW	Spain	Paper & Pulp
November 2019	NSC of Steam Turbine Siemens SST NG50/40-3 25MW	Spain	Paper & Pulp
November 2019	Manufacturing and delivery of spare parts Compressor Alstohm Rateau TSD65/65 SXA	Switzerland	Air separation
November 2019	Manufacturing and delivery of spare parts Steam Turbine ABB STAL TGB8 (HT) TGC8 (LT) 9,538 MW	Sweden	Power Plant
October 2019	Boroscope inspection Steam Turbine Man MAA10/MAC10 8,2 MW	Spain	Power
October 2019	Inspection of governor valve Steam Turbine Brown Boveri DGF Zi40 14,07 MW	The Netherlands	Waste
October 2019	Inspection of stop valve Steam Turbine KKK CF5 GS 1,28 MW	Sweden	Paper & Pulp
October 2019	Minor inspection of Steam Compressor ER80340 type RT28 Escher Wyss	Switzerland	Salt
October 2019	Revision of ventilator CV5300	Belgium	Chemical
September 2019	EMD and generator inspection Generator ABB HSG710 XS4	Sweden	Chemical
September 2019	NSC and revision of Steam Turbine Siemens SST 600 24,77 MW	Sweden	Power
September 2019	Major overhaul Steam Turbine Man DG71/080 22,89 MW	Sweden	Paper & Pulp
September 2019	Inspection and repair of rotor Steam Turbine Siemens NK40/56/126,5-B1DAS/II	Finland	Power
September 2019	Repair and manufacturing/delivery side plates & Turbine wheel Stal Laval DCDUM2070 22,45MW	Sweden	Paper & Pulp
September 2019	Major overhaul Steam Turbine Stal Laval DCDUM2070 22,45 MW	Sweden	Paper & Pulp
September 2019	Inspection of Steam Turbine Siemens SST 110 TWIN AFA 46GT6 4,106 MW	Sweden	Paper & Pulp
September 2019	Inspection and repair of Steam Turbine Siemens SST 600 - HNK 50/56/112 23,077 MW	Sweden	Power
September 2019	Manufacturing/delivery of coupling Steam Turbine Siemens 1DT 448-7DE02-Z 22,465 MW	Spain	Power
September 2019	Major overhaul turbo-alternator Thermodyn 821	France	Chemical
September 2019	NSC Steam turbine ABB/ACEC M2209.S 6,2MW	Sweden	Chemical
September 2019	Troubleshooting and repair of control valve Steam Turbine Fincantieri 36 CE 7,28 MW	Sweden	Power
September 2019	Inspection of Steam Turbine Ljungstrom 13 MW	Germany	Metalurgy
September 2019	Major overhaul ABB VE36A Turbine generator set	Spain	Paper & Pulp
August 2019	Electronical check of Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	Denmark	Power
August 2019	Revision of Thrust pads Steam Turbine Man Marc 2 8 MW	Belgium	Biomass Energy
August 2019	Manufacturing/delivery and repair of spare parts Steam Turbine Man Marc 2 - C10 5,72 MW	Belgium	Wood
July 2019	Inspection gas leakage Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	Denmark	Power
July 2019	NSC and compressor inspection Alstohm Rateau TSD65/65 SXA	Switzerland	Air separation
July 2019	Boroscope inspection of Steam Turbine Man Marc 2-B00 8,5 MW	Spain	Pulp & Paper
June 2019	Manufacturing and supply of Valve beam Steam Turbine Siemens SST 600 24,77 MW	Sweden	Power
June 2019	Repair, balancing and assembling of compressor parts Compressor FCM BELL E12K	Switzerland	Salt
May 2019	Alignment of generator Steam Turbine Man Marc 2 8MW	Belgium	Biomass Energy
May 2019	Vibration analysis gearbox Steam Turbine ABB AEG Kanis G20	Belgium	Pulp & Paper

May 2019	Bearing exchange Steam Turbine Man Marc 2 8 MW	Belgium	Biomass Energy
May 2019	NSC Steam Turbine ABB Stal VAX HP 25 B2528 29,2MW	Sweden	Pulp & Paper
May 2019	Inspection and repair of gearbox Steam Turbine ABB Stal VAX HP25 B2528 29,2 MW	Sweden	Pulp & Paper
May 2019	Cleaning of Turbo Compressor Rateau CM 2.80-3	France	Chemical
May 2019	Repair of Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	The Netherlands	Food
April 2019	NSC Steam Turbine Blohm+Voss AG GR36/35-5 6,24 MW	Spain	Power
April 2019	NSC Steam Turbine Siemens KKK AFA 46 GT5 Twin	Spain	Power
April 2019	Inspection and repair of Control Valve Steam Turbine Franco Tosi	The Netherlands	Waste
April 2019	Manufacturing of bearing pads Steam Turbine ABB AEG Kanis G20	Belgium	Pulp & Paper
April 2019	Installation of electrical overspeed device Steam Turbine Siemens 1DT 448-7DE02-Z 22,47 MW	Spain	Power
April 2019	Major inspection of Steam Turbine Siemens 1DT 448-7DE02-Z 22,47 MW	Spain	Power
April 2019	Manufacturing of new Turbine rotor Steam Turbine Stal Laval DDM2070 30MW	Sweden	Pulp & Paper
April 2019	NSC Steam Turbine Stal Laval DCDUM2070 22,45 MW	Sweden	Pulp & Paper
March 2019	Scanning of 2 rotors and bullgear Turbo Compressor Demag VK20	France	Chemical
March 2019	Hot alignment check Steam Turbine MAN Marc 2 B00 2,0 MW	Spain	Pulp & Paper
March 2019	Manufacturing , supply of spare parts and Stor Revision of Steam Turbine STAL-LAVAL DDM2070 30MW	Sweden	Pulp & Paper
March 2019	NSC Steam Turbine Siemens SST-600 HNK 50-56-112 27,2 MW	Sweden	Power
March 2019	Measurement controls Steam Turbine ABB VE36A 8,64 MW	Spain	Pulp & Paper
March 2019	Troubleshooting Steam Turbine G2 Stal DDSV 2072 20 MW	Sweden	Power
March 2019	Inspection and repair of generator Alsthom RN 144-87 6000 KVA	France	Chemical
March 2019	Inspection rotor generator Steam Turbine Ahlsthom 4,5 MW	France	Chemical
March 2019	Repair of tilting pads bearings	Italy	Chemical
March 2019	Troubleshooting gas turbine Rolls Royce Allison 501KB5 3,5 MW	The Netherlands	Food
March 2019	Overhaul of control valve and extraction valves ABB Stal VAX HP 25 B2528 29,2 MW	Sweden	Pulp & Paper
February 2019	Revision of Thrust pads Steam Turbine Man Marc 2 8MW	Belgium	Biomass Energy
February 2019	Troubleshooting Steam Turbine Man Marc 2 8 MW	Belgium	Biomass Energy
February 2019	Equipment and erection Steam Turbine Siemens SST-300 27,4 MW	Sweden	Pulp & Paper
February 2019	Inspection of Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	The Netherlands	Food
February 2019	Manufacturing and delivery of spare parts Steam Turbine KKK AFA GT44GTA 2,3 MW	Sweden	Pulp & Paper
January 2019	Overhaul Control and Extraction Valves Steam Turbine ABB Stal VAX HP 25 B2528 29,2 MW	Sweden	Pulp & Paper
January 2019	Revision of Thrust pads Steam Turbine Man Marc 2 8MW	Belgium	Biomass Energy
January 2019	Troubleshooting Steam Turbine Man Marc 2 8 MW	Belgium	Biomass Energy
January 2019	Inspection Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	The Netherlands	Food
January 2019	Manufacturing and supply of spare parts Steam Turbine KKK AFA GT4A GTA 2,3 MW	Sweden	Pulp & Paper
January 2019	Inspection Generator Leroy Somer A56BMDL145 9100 KVA	Sweden	Power
January 2019	Major overhaul Steam Turbine Fincantieri 36 CE 7,28 MW	Sweden	Power
December 2018	Overhaul Centrifugal Compressor GHH Volko 4	Germany	Automotive
December 2018	Commissioning of Woodward governor Steam Turbine SHINKO DNG62B-65 3,715 MW	Sweden	Power

December 2018	NSC Steam Turbine ABB VE36A 8,64 MW	Spain	Pulp & Paper
December 2018	Safety test Steam Turbine Stal Laval DDV 2070 25 MW	Sweden	Power
December 2018	Major overhaul Steam Turbine Stal Laval DDV2070 25 MW	Sweden	Power
December 2018	Manufacturing of spare parts and Major overhaul Steam Turbine Stal Laval DDM2070 30 MW	Sweden	Pulp & Paper
December 2018	Major overhaul Steam Turbine Siemens SST-300 27,4 MW	Sweden	Pulp & Paper
December 2018	NSC Steam Turbine Siemens SST-300 27,4 MW	Sweden	Pulp & Paper
December 2018	NSC Steam Turbine Stal Laval DCDUM 2070 22,45 MW	Sweden	Pulp & Paper
December 2018	Maintenance of Centrifugal Compressor C095-03000-01	Belgium	Chemical
December 2018	Maintenance of Centrifugal Compressor Samsung Techwin SE-45N	Belgium	Chemical
December 2018	Maintenance of Centrifugal Compressor Atlas Copco GT123L4K1	Belgium	Chemical
December 2018	Rewinding of stator winding SIEMENS generator SGEN 5-100A-4P	Sweden	Pulp & Paper
November 2018	Repair of set bearings Steam Turbine Brown Boveri DGF 2i 40 14,95 MWA	The Netherlands	Waste
November 2018	Manufacturing and delivery of valve spindle Steam Turbine Siemens ABB Twin Stal HP/LP SST 700 36,6 MW	Sweden	Power
November 2018	Major overhaul and supply of spare parts Steam Turbine Stal Laval DDM2070 30 MW	Sweden	Pulp & Paper
November 2018	Inspection of Steam Turbine Brown Boveri DGI 500/630 10 MW	Norway	Pulp & Paper
October 2018	Vibration measurement Steam Turbine MAN Turbo MARC 2-H02 9,33 MW	Sweden	Power
October 2018	Boroscope inspection of Steam Turbine Siemens SST-300 GE 21,54 MW	Sweden	Pulp & Paper
October 2018	Standard overhaul of hydraulic speed governor KALB Steam Turbine Blohm & Voss Marc 2 - C01 7,795 MW	Sweden	Waste
October 2018	Inspection of Steam Turbine Brown Boveri DGF 2i 40 14,9 MW	The Netherlands	Waste
October 2018	Inspection and overhaul of speed governor Turbine Sulzer Escher Wyss NGN 560 1,07 MW	France	Chemical
October 2018	Delivery of bolts Steam Turbine Siemens SST-300 27,4 MW	Sweden	Pulp & Paper
October 2018	Troubleshooting Steam Turbine M+M Mini 0,5 MW	The Netherlands	Agragian
September 2018	Troubleshooting Steam Turbine Man Marc 2-B00 8,5 MW	Spain	Pulp & Paper
September 2018	Repair of bearings Steam Turbine Siemens Siemens SST-600 KNK 50/56/112 23,077 MW	Sweden	Power
September 2018	Supply of valve spindles Steam Turbine Siemens SST-600 KNK 50/56/112 23,077 MW	Sweden	Power
September 2018	Delivery of studs/nuts/spacer bushes Steam Turbine ABB AEG KANIS G20	Belgium	Pulp & Paper
September 2018	Repair of active thrust tilting pads Steam Turbine Man Marc 2-B00 2,0 MW	Spain	Pulp & Paper
September 2018	Delivery of spare parts Steam Turbine Man Marc 2-B00 2,0 MW	Spain	Pulp & Paper
September 2018	Inspection Governor Valve Steam Turbine Franco Tosi 23,45 MW	The Netherlands	Waste
September 2018	Inspection of Steam Turbine Siemens SST-600 24,77 MW	Sweden	Power
September 2018	NSC and safety check Steam Turbine Siemens SST-300GE 21,154 MW	Sweden	Pulp & Paper
September 2018	Inspection of compressor flow path HV Turbo KA 10	The Netherlands	Waste
August 2018	Minor Inspection of Steam Turbine Man Marc 2 C10 5,72 MW	Belgium	Wood Industry
July 2018	Replacement of Vaup convertor Steam Turbine Siemens SST 110 4,4 MW	Sweden	Power
July 2018	Inspection of Steam Turbine BBC DGF 2i 40 14,95 MW	The Netherlands	Waste
July 2018	Inspection of stopvalve Steam Turbine ABB AEG KANIS G20	Belgium	Paper Plant
July 2018	Mechanical inspection excitation Steam Turbine BBC DEG 2i 44 26,8 MW	The Netherlands	Waste
June 2018	NSC Steam Turbine Siemens SST 600 ENG63/63 49,6 MW	Spain	Power

June 2018	NSC Steam Turbine Siemens SST 400 - CE240 36,6 MW	Spain	Power
June 2018	delivery of Lube oil pump Steam Turbine Worthington R2R	The Netherlands	Refinery
June 2018	Inspection and repair of coupling and gearbox Steam Turbine Blohm & Voss Marc2-C01 7,795 MV	Sweden	Waste
June 2018	Repair of bearings Compressor Allis Chalmer 262-C-2001	Norway	Paper Mill
June 2018	NSC Steam Turbine Man Marc 4 C12 21,4 MW	Spain	Paper Mill
June 2018	Inspection of Turbo compressor Sulzer BBC 111-4AEK	Switzerland	Salt Mine
June 2018	Repair of bearings Steam Turbine Siemens SST300 GE 21,154 MW	Sweden	Paper Mill
June 2018	On site Scanning and 3-D modelling of Nitrogen Compressor GT050 N4K1	France	Chemical
June 2018	NSC and inspection of Steam Turbine Babcock Borsig Power M63-G70 9,552 MW	Sweden	Power
June 2018	Inspection of Steam Turbine Man Marc 2 - 8 MW	Belgium	Bio Energy
June 2018	Delivery and installation of new control system Steam Turbine Siemens SST-110 Twin AFA 46 GT6 - 4,106 MW	Sweden	Pulp Mill
June 2018	Overhaul of Steam Turbine Siemens SST-110 Twin AFA 46 GT6 - 4,106 MW	Sweden	Pulp Mill
June 2018	Revision of Air Compressor Escher Wyss 90/4a EK	Switzerland	Salt Mine
June 2018	repair and installment of Gas Regulation Valve Gas Turbine Solar Centaur 3,5 MW	Germany	Automotive Plant
May 2018	NSC Steam Turbine Thyssen Krupp Marc 2B00 4,2 MW	Spain	Paper Mill
May 2018	Manufacturing and delivery of interstage seal Turbo Compressor Sulzer BBC 111-4AEK	Switzerland	Salt Mine
May 2018	Adjustment of bracket bearing Steam Turbine Siemens DGF 2i 40 14,95 MW	The Netherlands	Waste
May 2018	Spare parts check Air Compressor Rateau SM55-45-30	Switzerland	Gas Industry
May 2018	Inspection of Steam Turbine Man Turbo MARC2-B00/BHS Cincinnati RTP 56 II 8,5 MW	Spain	Paper Plant
May 2018	Delivery of new sunwheel gearbox Steam Turbine Man Turbo Marc 4-H03 20,02 MW	Sweden	Power
May 2018	NSC Steam Turbine ABB Stal HP25 29,2 MW	Sweden	Paper Mill
April 2018	Inspection and repair of 2 shaft seals Steam Turbine Stal DDM2070 30 MW	Sweden	Pulp Mill
April 2018	Delivery and installation of 2 trip blocs and control blocs + overhaul of Stop Valve and actuators Steamturbine	The Netherlands	Biorefinery
April 2018	Delivery of speed governor AEG Steam Turbine AEG Kanis GE20 2 MW	Sweden	Waste
March 2018	Supply of converter Steam Turbine Siemens SST 110 4,4 MW	Sweden	Power
March 2018	Repair of oil leakage extraction valve Steam Turbine Stal Laval DDmM60 10 MW	Sweden	Paper Mill
March 2018	Disassembly and assembly of generator Steam Turbine Stal Laval DDmM60 10 MW	Sweden	Paper Mill
March 2018	NSC Steam Turbine Siemens 1DT 448-7DE02-Z 22,465 MW	Spain	Power
March 2018	Supply of spare parts Steam Turbine KKK AFAGT4GTA 2,3 MW	Sweden	Paper Mill
March 2018	NSC Steam Turbine Siemens SST-600 HNK 50/56/112 23,077 MW	Sweden	Power
March 2018	NSC Steam Turbine Shinko DNG62B-65 3,75 MW	Sweden	Power
March 2018	Supply of 2 sets of bearings Steam Turbine Elliott 2EG-4	France	Food Industry
March 2018	Inspection of hydraulic actuator Voith Steam Turbine KKK AFAGT4GTA 2,3 MW	Sweden	Paper Mill
March 2018	Problem solving gearbox Steam Turbine Man Turbo Marc 4-H03 20,02 MW	Sweden	Power Plant
February 2018	Safety test Steam Turbine Stal Laval DDV 2070 20 MW	Sweden	Power
February 2018	Check of valve Steam Turbine KKK AFAGT4GTA 2,3 MW	Sweden	Paper Mill
February 2018	Repair of bearings Fan Fläkt Wood Oy	Sweden	Biorefinery
February 2018	Bearing repair Borsing Compressor C202	Italy	Chemical Plant

January 2018	NSC Steam Turbine Siemens SST 110 4 MW	Sweden	Pulp Mill
January 2018	NSC Steam Turbine Siemens SST 110 4,4 MW	Sweden	Power
January 2018	NSC and safety checks Steam Turbines AEG Kanis GE 20 2,0 mW and B+V Marc 2-C01 7,795 MW	Sweden	Waste
January 2018	Inspection HP valve Steam Turbine Alsthom ABB/ACEC 6,2 MW	Sweden	Chemical Plant
January 2018	Check of concentricity and perpendicularity to generator shaft of BHS-Cincinnati RTP 56II Satellite wheel Steam Turbine Man Turbo Marc 2-B00 8,5 MW	Spain	Paper Plant
January 2018	Repair of collector pump side Stal Laval DDV 2070 25 MW	Sweden	Power Plant
December 2017	Replacement and machining of strips rotor	Finland	
December 2017	Inspection NDE Bearing Steam Turbine SST 600 25 MW	Sweden	Power
December 2017	Major overhaul of Steam Turbine Stal Laval DDV2072 20MW	Sweden	Power
December 2017	Turbine & generator revision Steam Turbine Stal Laval DDMM60 B2072 10 MW	Sweden	Paper Mill
December 2017	Major overhaul Steam Turbine Man Turbo Marc 4-H03 20,02 MW	Sweden	Power
December 2017	Inspection and repair of bearings Air Compressor Booster	Italy	Chemical Plant
December 2017	Isolators/relays tests generator Steam Turbine Man Turbo MARC 2-H02 9,33 MW	Sweden	Power
November 2017	Delivery of spare parts Steam Turbine Shinko DNG62B-65 3,75 MW	Sweden	Power
November 2017	Minor inspection of Gas Turbine Allison 501 KB5 3,5 MW	Denmark	Power
November 2017	Minor Inspection of Steam Turbine MAN Marc 2-B00 2,0 MW	Spain	Paper Mill
November 2017	Delivery and installment of parts Steam Turbine ACEC M2209.S 6,2 MW	Sweden	Chemical Plant
November 2017	EMD measurement generator ABB HSG 710 XS4 Steam Turbine ACEC M2209.S 6,2 MW	Sweden	Chemical Plant
November 2017	Major overhaul Steam Turbine Siemens SST 600 HNK 50/56/112 23,077 MW	Sweden	Power
November 2017	Changement of the regulating Valve and revision of Voith actuator Steam Turbine Man Marc 2 8 MW	Belgium	Bio Energy
November 2017	Installation of Vibro control 920 Steam Turbine Siemens KKK Twin CA 56	Belgium	Waste
November 2017	Inspection and revision of Steam Turbine Siemens KKK Twin CA 56	Belgium	Waste
October 2017	Inspection of Steam Turbine Fincantieri 36 CE 7,28 MW	Sweden	Power
October 2017	repair of set of bearings fan Fläkt Wood Oy KEXRK-85/1580-XX-H-RDO	Sweden	Bio Refinery
October 2017	Engineering & Visualisation Rotor Dynamics Compressor KKK SF0 7,1/9,0	Belgium	Chemical Plant
October 2017	Inspection/3D scan/Modelling/balancing of impeller and shaft	Sweden	Bio Refinery
October 2017	Reinstallment of housing Allis Chalmer Compressor R62-C-2001	Norway	Paper Mill
October 2017	Inspection and repair of Steam Compressor Escher Wyss ER80340 Type RT 28	Switzerland	Salt Mine
October 2017	inspection and repair of bearings, delivery of spare parts Steam Turbine Siemens KKK ST-110 AFA6 CFR5 2 MW	Belgium	Waste
September 2017	Troubleshooting/vibration measurement Steam Turbine ABB AEG Kanis G20	Belgium	Paper Plant
September 2017	Troubleshooting Steam Turbine Siemens TG 2 9 MW	The Netherlands	Waste
September 2017	Inspection and repair of bearings Steam Turbine Man Marc 2 8 MW	Belgium	Bio Energy
September 2017	Delivery and installment of new coupling + regulating valve Steam Turbine Siemens SST 600 24,77 MW	Sweden	Power Plant
September 2017	Major overhaul Steam Turbine Shinko DNG62B-65 3,75 MW	Sweden	Power
August 2017	Delivery of 1 set bearings Elliot Turbine 2EPG4 Modele E	France	Food Industry
August 2017	Overhaul of Sulzer compressor GHH TKdb 5/5-L	Germany	Automotive Plant
July 2017	Major overhaul generator ELIN EBG typ HTM-180Z04 Steam Turbine Man Turbo Marc 2-H02 9,33 MW	Sweden	Power plant
July 2017	Bearing De+NDE repair steam turbine Man MARC4-H03 20,02 MW	Sweden	Power Plant

July 2017	Major overhaul Turbine Escher Wyss type NGN50 1,07 MW	France	Chemical Plant
June 2017	Overhaul Rotor PT4403A coppus RLH Steam turbine	The Netherlands	Chemical Plant
June 2017	Delivery of off set bearing 0 210 mm Gearbox Steam Turbine Siemens SST 300 GE40A 28,3 MW	Sweden	Pulp Mill
June 2017	Inspection Steam Turbine ABB M2209 S 6,2Mw	Sweden	Chemical Plant
June 2017	Minor inspection steam turbine Siemens SST 600 24,77 Mw	Sweden	Power Plant
May 2017	Inspection of generator, configuration, delivery and instalment of voltage controller Steam Turbine Siemens SST 110 4,4 Mw	Sweden	Power Plant
May 2017	Manufacturing of retaining rings coupling	Belgium	Chemical Plant
May 2017	Inspection of Turbo compressor Sulzer BBC 111-4AEK	Germany	Automotive Plant
May 2017	Inspection ot steam turbine ABB STAL VAX HP25 29,2 Mw	Sweden	Paper Mill
May 2017	NSC Steam Turbine Man Turbo Marc4-H03	Sweden	Power Plant
May 2017	Technical consultancy AE&E 9Mw	The Netherlands	Waste Plant
May 2017	Supervision AE&E 9Mw Cond.extraction steam turbine	The Netherlands	Waste Plant
May 2017	Delivery of bearing seals generator Siemens SGEN 5-100A-4P	Sweden	Pulp Mill
May 2017	Intermedium Inspection steam turbine Man Marc 2 8 Mw	Belgium	Bio Engery
April 2017	Gearbox inspection steam turbine Siemens ABB Twin Stal HP/LP SST 700 36,6 Mw	Sweden	Power Plant
April 2017	NSC steam turbine Fincantieri 36 CE 7,28Mw	Sweden	Power Plant
April 2017	rotor vibration analysis calculation AE&E 9 Mw Cond. Extraction turbine	The Netherlands	Waste Plant
April 2017	maintenance on rotating equipment compressor Sulzer Escher Wyss 64/5 nr 793 Groupe TC9	France	Chemical Plant
April 2017	Nsc Steam Turbine Stal DDV2070+DDSV2072 20 :25 MW	Sweden	Power Plant
April 2017	Reverse engineering Hydraulic units Siemens T8512 EHNG 40/32/40	The Netherlands	Bio Chemical plant
March 2017	NSC Steam Turbine Siemens SST-110 4 MW	Sweden	Pulp Mill
March 2017	Delivery of speed pick up Steam Turbine SST-110 4,4 MW	Sweden	Power
March 2017	Adjustment of start system Gas Turbine Solar Centaur 3,5 MW	Germany	Automotive Plant
March 2017	Inspection and standard overhaul oilpump and repair of bearings Steam Turbine Siemens SST-300 GE40A 28,3 MW	Sweden	Pulp Mill
February 2017	Troubleshooting control system Steam Turbine KKK AFAGTAGTA 2,3 MW	Sweden	Paper Mill
February 2017	NSC Steam Turbine Siemens SST-600 25 MW	Sweden	Power
February 2017	NSC Steam Turbine Siemens SST-300 GE40A 28,3 MW	Sweden	Pulp Mill
February 2017	Repair of shaft seal Steam Turbine KKK AFAGTAGTA 2,3 MW	Sweden	Paper Mill
February 2017	Supply and installment of overspeed device Voith Steam Turbine Siemens SST-110 4,4 MW	Sweden	Power Plant
February 2017	Supply of drain valves Steam Turbine Siemens SST-300 GE40A 28,3 MW	Sweden	Pulp Mill
February 2017	Troubleshooting AFA Control Valve Steam Turbine Siemens SST-110 4 MW	Sweden	Pulp Mill
February 2017	Delivery/manufacturing/repair of spare parts Steam Turbine Siemens SST-300GE 21,15 MW	Sweden	Paper Mill
February 2017	Delivery/manufacturing/repair of spare parts Steam Turbine ABB Stal Vax HP25 29,2MW	Sweden	Paper Mill
January 2017	Troubleshooting Steam Turbine KKK CF5 GS 1,28 MW	Sweden	Paper Mill
January 2017	Exchange of Woodward of Gas Turbine Solar Centaur 3,5 MW	Germany	Automotive Plant
January 2017	Start-up of Gas Turbine RR Allison KB 5	Netherlands	Food Industry
November 2016	Inspection of Steam Turbine Siemens SST100 4.4 MW	Sweden	Power
November 2016	Inspection of Sulzer Centrifugal Compressor GHH TKdb 5/5-L	Germany	Automotive Plant

November 2016	Inspection of Steam Turbine Esscher Wyss NG50 1.070 MW	France	Chemical Plant
November 2016	Repair of impeller Allis Chalmer Compressor 262-C2001	Norway	Paper Mill
November 2016	Start up of turbine KKK AFA GT44 FTA 2.3 MW	Sweden	Paper Mill
November 2016	Engineering/manufacturing of spare parts and repair of impeller ABB Flakt	Norway	Paper Mill
November 2016	Inspection of Sulzer compressors	Germany	Automotive Plant
November 2016	Vibration measurement Steam Turbine Man Turbo Marc2-H02 9.33 MW	Sweden	Power Plant
November 2016	Condition monitoring of Sulzer compressor	Norway	Paper Mill
November 2016	Changement of bearing and seal Gas Turbine Rolls Royce Allison 501KB5 3.5 MW	Netherlands	Food Industry
November 2016	Start up of turbine Siemens ABB Twin Stal HP/LP SST-700 36.6 MW	Sweden	Power
November 2016	Inspection Steam Turbine Siemens SST100 KKK/CFR AFA 2MW	Belgium	Waste
November 2016	Revision of Steam Turbine Siemens SST-300/GE40A 28.3 MW	Sweden	Pulp Mill
November 2016	Engineering/manufacturing of spare parts & repair of rotor Compressor KKK SFO7.1/9.0	Belgium	Materials Recycling Plant
October 2016	Inspection and repair of Woodward actuator	Sweden	Chemical Plant
October 2016	Changement of axial bearing Steam Turbine MAN Marc 2 8MW	Belgium	Bio Energy
October 2016	Service on 2 fans Fläkt Wood Oy KEXRK-85/1580-XX-G-H-RDO	Sweden	Biorefinery
October 2016	Inspection and repair of generator ABB HSG 710XS4 6.2 MW	Sweden	Chemical Plant
October 2016	Engineering/manufacturing of new coupling Compressor Allis Chalmer 262 - C2001	Norway	Paper Mill
October 2016	Major overhaul of Steam Turbine KKK AFA GT44 FTA 2.3 MW	Sweden	Paper Mill
August 2016	Major overhaul of Steam Turbine Siemens SST-300GE 21,154 MW	Sweden	Paper Mill
August 2016	Engineering/manufacturing and installment of new coupling Steam Turbine Man Turbo Marc2 - H02 9.33 MW	Sweden	Power
August 2016	Inspection and repair of bullgear gearbox Steam Turbine Steam Turbine Siemens ABB Twin Stal HP/LP SST 700 36.6MW	Sweden	Power
August 2016	Engineering/manufacturing of new tilting pads bearing DE Steam Turbine Siemens ABB Twin Stal HP/LP SST 700 36.6MW	Sweden	Power
August 2016	Vibration measurement Steam Turbine Man Marc 2 8MW	Belgium	Bio Energy
August 2016	Repair of nozzle unit Steam Turbine AEG Kanis KR32F 15MW	Finland	Power
August 2016	Annual inspection and repair of Gas Turbine Rolls Royce Allison 501KB5	Netherlands	Food Industry
August 2016	Start-up of Steam Turbine SST-600 25MW	Sweden	Power
August 2016	Engineering and manufacturing of spare parts Compressor Alhstom TSD65/65 SXA	Switzerland	Gas Industry
August 2016	Delivery/configuration of vibration protection device + converter Steam Turbine Siemens SST 110 4.4 MW	Sweden	Power
August 2016	vibration measurement and replacement bearings Steam Turbine Man Marc 2 8MW	Belgium	Bio Energy
August 2016	Engineering/manufacturing of new coupling Steam Turbine Man Turbo MARC 2 -H02 9.33MW	Sweden	Power Plant
July 2016	Troubleshooting Steam Turbine Siemens SST110 4,4 MW	Sweden	Power
July 2016	Troubleshooting Steam Turbine Man Marc 2 8MW	Belgium	Bio Energy
July 2016	Inspection leakage DE turbine bearing Steam Turbine Siemens SST-600 HNK 50/56 25.4 MW	Sweden	Power
July 2016	Inspection and revision Compressor parts Blower KKK- SFO7-1/9.0	Belgium	Materials Recycling Plant
July 2016	inspection of Compressor parts Allis Chalmer 262 - C2001	Norway	Paper Mill
July 2016	repair of turbine parts + installation on site Steam Turbine Stal DMM2070 12MW	Sweden	Chemical Plant
June 2016	Troubleshooting Steam Turbine Man Turbo MARC 2-H02 9,33 MW	Sweden	Power
June 2016	NSC + major overhaul Steam Turbine ABB Stal Vax HP25 B2528 29,2 MW	Sweden	Paper Mill

June 2016	Exchange of a Gas Turbine Solar Centaur 3,5 MW	Germany	Automotive
June 2016	Installation of delivered parts Steam Turbine SST 600 T6374 24,77MW	Sweden	Power
June 2016	Inspection of gearbox LP and HP Steam Turbine Siemens ABB Twin Stal HP/LP	Sweden	Power
June 2016	repair of bearings Compressor 90/4a EK	Switzerland	Salt Mine
Mai 2016	Troubleshooting Steam Turbine Siemens SST100 KKK/CFR AFA 2 MW	Belgium	Waste
Mai 2016	Inspection of compressor Alstohm Rateau TSD65/65 SXA	Switzerland	Gas Industry
Mai 2016	Bearing inspection of Steam Turbine Shinko DNG 62B-65 3,65MW	Sweden	Power
Mai 2016	NSC Steam Turbine KKK AFAGT4GTA 2,3 MW	Sweden	Paper Mill
Mai 2016	Upgrade Turbine Controls Gas Turbine Solar Centaur 3,5 MW	Germany	Automotive
Mai 2016	Re-coating compressor part of Gas Turbine Allison 501KB5 3,5 MW	Denmark	Power
Mai 2016	Installation of overhauled Centrifugal Compressor Siemens Demag VK32-3EX	Russia	Chemical Plant
April 2016	Assistance activity on Steam Turbine GE-Turbodyne 40MW	Netherlands	Power
April 2016	Vibration measurement Steam Turbine Man Turbo MARC2-H02 9,33 MW	Sweden	Power
April 2016	NSC Steam Turbine Siemens SST 600 - HNK 50/56 25,35 MW	Sweden	Power
April 2016	NSC Steam Turbine Siemens SST 110 4MW	Sweden	Pulp Mill
April 2016	Inspection and oil leakage repair Steam Turbine Stal DDM2070 30 MW	Sweden	Pulp Mill
April 2016	Delivery of parts Steam Turbine Siemens SST 600 25MW	Sweden	Power
April 2016	Troubleshooting Gas Turbine Allison Controls KB501 3,5 MW	Netherlands	Paper Mill
April 2016	Inspection of split line Steam Turbine Stal Laval DDV 2070 25 MW	Sweden	Power Plant
April 2016	NSC Steam Turbine Shinko DNG 62B-65 3,65 MW	Sweden	Power
April 2016	Leaktest condensor Steam Turbine Skoda G6 KP-40-6,1 40MW	Sweden	Pulp Mill
March 2016	Minor overhaul of Steam Turbine ABB AEG Kanis G20	Belgium	Paper Plant
March 2016	Inspection of Blower Hoffman 75.103.B	Belgium	Steel Plant
February 2016	Troubleshooting Woodward & regulating properties Steam Turbine Nadrowski 1,7 MW	Sweden	Power
February 2016	Inspection of bearings & impeller Air Compressor KKK SFO 7,1/9,1	Belgium	Recycling Plant
February 2016	Overhaul of Centrifugal Compressor Siemens Demag VK32-3EX	Russia	Chemical Plant
January 2016	Troubleshooting Allias Chalmers Compressor 262-C2001	Norway	Päper Mill
January 2016	Annual 8000h inspection Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	Denmark	Power
January 2016	Investigation vibrations Steam Turbine Blohm & Voss Marc 2-C01 7,795 MW	Sweden	Waste Plant
January 2016	Alignment and bearing inspection Steam Turbine Siemens ABB Twin Stal HP/LP SST700 36,6 MW	Sweden	Power Plant
January 2016	Re-assembly and installment of GHH Main Air Compressor TD 4,5/5 BAR	Italy	Chemical Plant
January 2016	Replacement of valve spindles Steam Turbine Siemens SST600 25 MW	Sweden	Power
December 2015	Reverse engineering and manufacturing of spare parts Steam Turbines Siemens KKK CF5DS/KKK AF8GS/G250/2	Sweden	Refinery
December 2015	Rotor cleaning and HSB rotor Steam Turbine Siemens ABB Twin Stal HP/LP SST700 36,6 MW	Sweden	Power Plant
December 2015	Inspection of Steam Turbine AEG Kanis GE50A(K) 9,05 MW	Netherlands	Carbon Industry
December 2015	Replacement of damaged silencer panels inlet sound silencer G200 Turbocompressor	Germany	Waste plant
December 2015	Boroscope inspection Gas Turbine Rolls Royce Allison 501KB5 3,5 MW	Netherlands	Food Industry
December 2015	Inspection & repair of rotor Centrifugal Compressor Elliot K601	Sweden	Refinery

November 2015	NSC Steam Turbine KKK Siemens CFR3/AFA6 GT6 2,64 MW	Germany	Chemical Plant
November 2015	Inspection of gearbox and installment of new oil pump Steam Turbine Siemens SST300 GE40A 28,3MW	Sweden	Pulp Mill
November 2015	Repair of components GHH Main Air Compressor TD 4,5/5 BAR	Italy	Chemical Plant
November 2015	Shaft seal repair Steam Turbine Stal DDSV 2072 20 MW	Sweden	Power
November 2015	Overhaul of Turbine Compressor Brown Boveri - Sulzer type 90/4a EK	Switzerland	Salt Plant
October 2015	Inspection of Steam Turbine GEM DGSS28P 6,5 MW	France	Chemical Plant
October 2015	Overhaul of anti surge valve Sulzer Turbo Compressor ER80340 type RT28	Switzerland	Salt Plant
October 2015	Overhaul of Sulzer Turbo Compressor ER80340 type RT28	Switzerland	Salt Plant
October 2015	Installment of new Control Valves Steam Turbine Alstohm	Netherlands	Waste
October 2015	Reverse engineering and manufacturing of Control Valves Alstohm Steam Turbine	Netherlands	Waste
October 2015	Diagnosis & intervention on the controls of Steam Turbine Financieri 2 MW	Italy	Power
October 2015	Bearing repair HP16 of Steam Turbine Siemens ABB Twin Stal 36,6 MW	Sweden	Power
October 2015	Inspection of Compressor ABB/Western C2001	Norway	Paper Mill
October 2015	Troubleshooting oil leakage Gas Turbine RR Allison KB501 3,5 MW	Netherlands	Paper Mill
September 2015	Manufacturing and delivery of parts Sulzer Steam Compressor ER80340 RT28	Switzerland	Salt Plant
September 2015	Major inspection turbine control system Steam Turbine SST 110 4MW	Sweden	Pulp Mill
September 2015	Bearing split line inspection/repair Steam Turbine Stal DDM 2070 30 MW	Sweden	Pulp Mill
September 2015	Repair of rotor and impeller Air Compressor KKK SFO 7,1/9,0	Belgium	Recycling Plant
September 2015	Assembly of control valve and servo Steam Turbine Siemens SST100 4 MW	Sweden	Pulp Mill
September 2015	Inspection of KKK Compressor SFMG 5,6A	Sweden	Paper Mill
September 2015	Repair of servo Steam Turbine SST 600 25 MW	Sweden	Power
September 2015	Assembly of Steam turbine SST 100 4 MW	Sweden	Pulp Mill
September 2015	Commissioning and assistance Steam Turbine Alstohm type TM2 24,5/48,5 9,2 MW	France	Waste
September 2015	Installment of new dampers Inlet Sound Silecer turbo compressor G200	Germany	Waste
September 2015	Rotor repair Sulzer RC-4A-4N-81	France	Paper Plant
September 2015	Inspection and repair of valve beam Steam Turbine SST 600 25 MW	Sweden	Power
September 2015	Bearing inspection Steam Turbine SST 600 NK63/3,2 36,5 MW	Netherlands	Biomass
August 2015	Delivery of new gear Steam Turbine Siemens SST 100 4MW	Sweden	Pulp Mill
August 2015	Start-up and functionality check control Steam Turbine SST 600 25 MW	Sweden	Power
August 2015	Major overhaul Steam Turbine Alstohm type TM2 24,5/48,5 9,2 MW	France	Waste
August 2015	Yearly inspection Gas Turbine RR Allison 501 K 3 MW + testing of generator protection relays	Denmark	Power
August 2015	Demagnetisation and high speed balancing of turbine rotor Steam Turbine Alstohm typ TM2 24,5/48,5 9,2 MW	France	Waste
August 2015	Disassembly of old Compressor and Installment of Turbo Compressor Brown Boveri/Sulzer 90/4A EK	Switzerland	Salt Plant
August 2015	Machining of labyrinths Turbo Compressor Brown Boveri/Sulzer 90/4A EK	Switzerland	Salt Plant
July 2015	Bearing inspection Steam Turbine Peter Brotherhood Frame 20 10,75 MW	Spain	Power
July 2015	Bearing inspection Steam Turbine MAN Marc 2-BOO 2,5 MW	Spain	Paper Mill
July 2015	Inspection and repair of actuator Woodward PDG 29	France	Food Industry
July 2015	Supply of 2 sets of bearings Steam Turbine Elliott 2EG-4	France	Food Industry

July 2015	Inspection of Compressor IR	Germany	Automotive
July 2015	Bearing inspection Steam Turbine HP and LP Siemens ABB Twin Stal HP/LP SST700 36,6 MW	Sweden	Power
July 2015	Inspection of Main Air compressor unit GHH TKD 4,5/5 Bar	Italy	Chemical Plant
July 2015	Inspection of rotor Sulzer RC-4A-4N-81	France	Paper Plant
July 2015	Inspection of 2 rotors Compressor ABB/WESTERN C20001	Norway	Paper Mill
July 2015	Inspection of Steam Turbine Stal Laval G1 B-2073 12MW	Sweden	Pulp Mill
July 2015	Upgrade of Turbo Compressor Brown Boveri/Sulzer 90/4A EK	Switzerland	Salt plant
July 2015	Standard overhaul of Centrifugal compressor + replacement of coupling GHH TK 5/2 + TG 5/3	Germany	University
July 2015	Major overhaul Steam Turbine Alsthom type TM2 24,5/48,5 9,2 MW	France	Waste
July 2015	Inspection of B&V turbine MAN 1505 Kw 15,650 rpm	France	Chemical Plant
June 2015	Axial bearing check and bump test of rotor Steam Turbine Alsthom ABB/ACEC 6,2 MW	Netherlands	Chemical Plant
June 2015	Inspection and replacement of damaged panels in Inlet Sound Silencer Turbocompressor G200	Germany	Waste Plant
June 2015	Inspection Thrust Bearing Chlor Compressor Siemens	Netherlands	Chemical Plant
June 2015	Sandblasting and inspection of rotor Steam Turbine Escherwys RG 800	France	Chemical Plant
June 2015	Inspection and repair of stopvalve Steam Turbine Shinko DNG 62-+65 3,65MW	Sweden	Power
June 2015	Delivery of new spindle for ESV Valve Steam Turbine Shinko DNG 62B-65 3,65MW	Sweden	Power
June 2015	Major overhaul of Steam Turbine Shinko DNG 62B-65 3,65 MW	Sweden	Power
June 2015	Major overhaul of Steam Turbine MARC 2-B00 OMAA10 8,5MW	Spain	Paper Plant
Mai 2015	Inspection of Steam Turbine Blohm & Voss Marc 2 - C01 7,795 MW	Sweden	Waste
Mai 2015	Start-up of Centrifugal Compressor Rateau SM55-1	France	Chemical Plant
April 2015	Inspection of Steam Turbine Esscherwys typ RG800	France	Chemical Plant
April 2015	Supply of set of oil labyrinth seals and complete bearing house of Steam Turbine Blohm & Voss KR50/70-2 4,4 MW	Germany	Waste
April 2015	Inspection of gearbox Gas Turbine Allison KB501 3,5 MW	Netherlands	Paper Mill
April 2015	Inspection and overhaul of 3 Turbo Air Blowers Sulzer RC4-3N-80/RC4A-4N-80/RT56-1	Norway	Paper Mill
April 2015	Overhaul of Kalb speed governor	Sweden	Waste
April 2015	On site Installment of rotor Centrifugal Compressor Rateau SM55-1	France	Chemical Plant
April 2015	Inspection and testing of convertor VOITH 3/3	Sweden	Paper Mill
April 2015	Delivery and installation of supports pedestal generator bearing no 1 of steamturbine GEMCO DGSS28P 6,5 MW	France	Chemical Plant
March 2015	Inspection/repair of rotor centrifugal compressor Rateau SM55-1	France	Chemical Plant
March 2015	Supply of valve spindle Steam Turbine Siemens SST800 - 89,785 MW	Sweden	Power Plant
March 2015	Supply of HMI for turbine control systems Steam Turbine AEG Kanis 11,2 MW	Netherlands	Carbon Industry
March 2015	Visual inspection of impeller Centrifugal Compressor GHH TK 5/2 + TG5/3	Germany	University
March 2015	NSC Steamturbine Alsthom type TM2 24,5/48,5 9,2 MW	France	Waste Plant
March 2015	Engineering surge valve study Steam Compressor Sulzer RT28 ER80340	Switzerland	Salt plant
March 2015	Overhaul of 3 x Steam Turbine Dresser Coppus TF16	Sweden	Refinery
March 2015	Overhaul of Steam Turbine Siemens G200/2 1,848 MW	Sweden	Refinery
March 2015	Overhaul of Steam Turbine Siemens G250/2 1,78 MW	Sweden	Refinery
March 2015	Overhaul of Steam Turbine KKK AF8Gs 0,605 MW	Sweden	Refinery

March 2015	Overhaul of Steam Turbine KKK CF5Ds 0,625 MW	Sweden	Refinery
March 2015	Manufacturing and delivery of HT Bypass valve Steam Turbine Siemens SST800 89,785 MW	Sweden	Power
February 2015	Maintenance inspection Centrifugal Compressor Atlas Copco GT-032 L6K1	Italy	Chemical Plant
February 2015	Inspection of rotor Blower KKK AF SL9a	Italy	Chemical Plant
February 2015	Troubleshooting Steam Turbine Stal DDSV2072 20 MW	Sweden	Power
February 2015	Repair of rotor, bearings and seals Chlorine Gas Compressor Demag GD425	Sweden	Chemical Plant
January 2015	Delivery gaskets Steam Turbine Stal DM65 17,3 MW	Sweden	Biorefinery
January 2015	Delivery and installment of spare parts Gas Turbine Allison KB 501 3,5 MW	Netherlands	Paper Mill
January 2015	Check of generator Steam Turbine Siemens SST300GE 25 MW	Sweden	Pulp Mill
January 2015	Cleaning of steam strainer Steam Turbine Stal Laval DDTM2070 18,11 MW	Sweden	Pulp/Paper Mill
January 2015	NSC Steam Turbine Siemens ABB Twin Stal HP/LP SST700 36,6 MW	Sweden	Power
January 2015	NSC Steam Turbine Nadrowski B5S - 5+6 1,6 MW	Sweden	Power
January 2015	NSC Steam Turbine Stal DDSV 2072 20 MW	Sweden	Power
January 2015	NSC Steam Turbine KKK AFAGT4GTA 2,3 MW	Sweden	Paper Mill
January 2015	NSC Steam Turbine Siemens SST600 HNK 50/56 25,4 MW	Sweden	Power
January 2015	NSC Steam Turbine Dresser Rand Nadrowski 20878 G5DD+G 1,7 MW	Sweden	Power
January 2015	NSC Steam Turbine AEG Kanis GE 20 2MW	Sweden	Waste
January 2015	NSC Steam Turbine Man Marc 2-H01 7MW	Sweden	Power
January 2015	NSC Steam Turbine Siemens VA25-ATP1 11,85 MW	Sweden	Power Plant
December 2014	Revision and white metal coating of trust bearings Air Compressor KKK type SFO 9	Belgium	Recycling Plant
December 2014	Repair of off-set bearings Steam Turbine Siemens ABB Twin Stal HP/LP SST 700	Sweden	Power
December 2014	Delivery of spare parts Gas Turbine Rolls Royce Allison 501 K 3,0 MW	Denmark	Power
December 2014	Inspection of steam Turbine Stal DM 65 17,3 MW	Sweden	Biorefinery
December 2014	Major overhaul Steam Turbine KKK Siemens CFR3/AFA6 GT6 2,64 MW	Germany	Chemical Plant
December 2014	Vibration measurements Centrifugal Air Compressor GHH TK 5/2 + TG5/3	Germany	Technical University
December 2014	Nozzle inspection Steam Turbine Alstom TM290 4,4MW	France	Waste
November 2014	NSC Steam Turbine MAN MARC 2 2,0 MW	Spain	Paper Mill
November 2014	NSC Steam Turbine ABB G32 Siemens 12MW	Portugal	Sugar Mill
November 2014	Inspection and replacement of carbon rings Turbo Compressor Sulzer-Escher Wyss RT28-1	Italy	Chemical Waste
November 2014	Inspection and overhaul of Steam Turbine Stal DDM2070 30 MW	Sweden	Pulp Mill
November 2014	EMD Measurements on 2 Asea HS generators Steam Turbine Stal DDM2070 30 MW	Sweden	Pulp Mill
November 2014	Major overhaul Steam Turbine Siemens SST300GE 25 MW	Sweden	Pulp Mill
November 2014	NSC Steam Turbine Skoda R14 AO 14 MW	Sweden	Power
November 2014	NSC Steam Turbine Siemens SST800 72 MW	Sweden	Paper Mill
November 2014	Bearing inspection HP Steam Turbine Siemens ABB Twin Stal SST700 36,6MW	Sweden	Power
November 2014	Troubleshooting axial displacement Steam Turbine AEG Kanis GE20 2MW	Sweden	Waste
October 2014	Delivery of an Electro-Hydraulic Actuator control Woodward CPC2	The Netherlands	Activated carbon plant
October 2014	Start-up of Steam Turbine Stal DDSV 2072 - 20MW	Sweden	Power

October 2014	Troubleshooting Steam Turbine Siemens KKK AF6 G6a 3,0 MW	Sweden	Power
October 2014	Start-up of Steam Turbine Siemens SST 600 25 MW	Sweden	Power
October 2014	NSC Steam Turbine Siemens KKK CFR3/AFA6 GTA 2,64 MW	Germany	Chemical Plant
October 2014	NSC Centrifugal Compressors Atlas Copco GT032 L6K1 K101 and K102	Italy	Chemical Plant
October 2014	Various repairs Steam Turbine Siemens SST 300 GE40A 28,3 MW	Sweden	Pulp Mill
October 2014	Troubleshooting Gearbox of Steam Turbine Siemens SST 300GE 25 MW	Sweden	Paper Mill
October 2014	Troubleshooting Steam Turbine Stal DDM2070 30MW	Sweden	Pulp Mill
October 2014	Start-up & calibration of GHH Turboverdichter Centrifugal Compressor 5, Volko 5	Germany	Automotive plant
October 2014	Revision of actuator GHH Turboverdichter compr 5, Volko 5	Germany	Automotive plant
October 2014	Minor overhaul Steam Turbine Blohm & Voss Marc 2 - C01 7,795 MW	Sweden	Waste plant
October 2014	NSC Steam Turbine Siemens SST 300 GE40A 28,3MW	Sweden	Waste
October 2014	NSC Steam Turbine Blohm+Voss Marc 2 - C01 7,795 MW	Sweden	Waste
September 2014	Non stop check SteamTurbine Blohm & Voss KR45/80-2 3,43 MW	Germany	Biomass
September 2014	Assistance minor overhaul steamturbine Siemens SST600 NK 63/32 36,5 MW	The Netherlands	Biomass
September 2014	Minor overhaul of steamturbine Siemens KKK AFA 6 G6a 3MW	Sweden	Power
September 2014	Inspection of steamturbine Tuthill Nadrowski C5DSII + TSG2-355 1,712 MW	Sweden	Power
September 2014	Seal inspection steamturbine Stal Laval DDSV 2072 18,82 MW	Sweden	Power
September 2014	Major overhaul steamturbine GTA Dresser Rand Nadrowski B554 2,7 MW	France	Waste plant
September 2014	Replacement of valve seat steamturbine STT 600 NK40/56 24.8 MW	Sweden	Power
September 2014	Repair of a Worthington R2R steam turbine process pump driver	The Netherlands	Refinery
September 2014	On site balancing electr motor / compressor Sulzer K 203	Italy	Lead Recycle plant
September 2014	Minor overhaul steamturbine KKK AF6 3 MW	Sweden	Power plant
August 2014	Major overhaul on Siemens backpressure steamturbine NG50/40-3 25MW	Spain	Paper mill
August 2014	Bearing inspection turbine Blohm & Vos Marc 4 - H04 15,9 MW	Sweden	Power
August 2014	Troubleshooting on a Siemens NKS 40/63-3 20.7 MW steam turbine	Denmark	Power plant
August 2014	Non stop check Tuthill Nadrowski C5DSII + TSG2-335 1.7 MW	Sweden	Power plant
August 2014	Hot alignment check Siemens ABB Twin Stal steam turbine LP/HP 16 VAX	Sweden	Power plant
August 2014	Inspection of 2 TAIKO Blowers RG - 350 W	France	Waste plant
August 2014	Supply and installation of 2 new spindles for regulation valve Siemens NG50/40-3 18MW	Spain	Paper mill
July 2014	Cleaning of LP nozzle & impeller KKK AFA4 G3A Tandem steam turbine	Germany	Waste plant
July 2014	Troubleshooting Dresser Rand 12D8878 1.4 MW steam turbine	Spain	Paper mill
July 2014	Main stopvalve inspection Siemens ABB Twin Stal turbine LP/HP 16 VAX	Sweden	Power plant
July 2014	Bearing inspection Blohm & Voss Marc 4-H04 15,9 MW steam turbine	Sweden	Power plant
July 2014	Revision GHH Turboverdichter compr 4, Volko 4 nr 120396	Germany	Automotive plant
June 2014	Yearly inspection RR Allison 501 KB5 gasturbine	Denmark	Power plant
June 2014	Inspection Atlas Copco GT032 L6K1 steam blower	Italy	Chemical plant
Mai 2014	Inspection/repair of rotor centrifugal compressor RATEAU SM55-1 C2716	France	Chemical plant
Mai 2014	Performance evaluation on 2 steamturbines Fincantieri 36 TE 3MW / 60 TE 2,6 Mw	Italy	Biomass plant
Mai 2014	Bearing inspection gearbox Siemens STT600 25.4 MW	Sweden	Power plant

Mai 2014	Installment new vibration measurement system SHINKO turbine DNG62B-65 3.65MW	Sweden	Power plant
Mai 2014	Inspection stop valve SHINKO turbine DNG62B-65 3.65MW	Sweden	Power plant
April 2014	Boroscope inspection/control valve inspection Siemens STT 600 NK40/56 24.8MW	Sweden	Power plant
April 2014	Upgrade control valve Siemens STT 600 NK40/56 24.8MW	Sweden	Power plant
April 2014	Troubleshooting control oil system Siemens STT300 GE40A 28.0MW	Sweden	Pulp mill
April 2014	Bearing inspection AEG Kanis Type G steam turbine 11.2MW	The Netherlands	Activated carbon plant
April 2014	Delivery and installment of spare parts Siemens STT100 CA35GT6	Germany	Power plant
April 2014	Inspection steam compressor Sulzer Escher Wyss RT28-1	Italy	Chemical waste plant
April 2014	Overhaul compressor Alstohm 55-45-30	Switzerland	Industrial gas
April 2014	High speed balancing of a rotor Blohm&Voss KR 50/70-2 4.4MW turbine	Germany	Waste plant
March 2014	Overhaul of a Brown Boveri 90/4A EK compressor	Switzerland	Salt mine
March 2014	Seal upgrade and design modification Siemens ACEC 10MW HP	Sweden	Chemical plant
March 2014	NSC /inspection/bearing repair on a Siemens ABB Twin Stal turbine HP/LP	Sweden	Power plant
March 2014	Supervising overhaul of a Atlas Copco compressor GT032T2K1	Sweden	Chemical plant
March 2014	Vibration analysis Turbine ABB G20 10MW	Belgium	Paper mill
March 2014	Troubleshooting control valve Stal DM65 17,3 MW	Sweden	Paper mill
February 2014	Generator/overspeed and vibration repair Indar BZKL/710/V-4 7100 KVA - 1500/1800RPM	Sweden	Power plant
February 2014	NSC SHINKO turbine DNG62B-65 3.65 MW	Sweden	Power plant
February 2014	Inspection valve Steam Turbine Dresser Rand Nadrowski B55-5 3,4 MW	Norway	Waste plant
January 2014	Installation vibrocontrol Siemens STT100 CA35GTA 30MW	Germany	Power plant
January 2014	Inspection generator Indar BZKL/710/V-4 7100KVA - 1500/1800RPM	Norway	Waste plant
January 2014	Overhaul Worthington R2R	The Netherlands	Refinery
January 2014	Supply of Revak II bearing lubrication system	The Netherlands	Refinery
January 2014	Inspection Siemens SST600 NK40/56 25MW	Sweden	Power plant
December 2013	Installation iginitors on a Allison 501K Gas Turbine	Denmark	Power plant
December 2013	Troubleshooting on a Siemens SST100 CA35GTA 30MW	Germany	Power plant
December 2013	Inspection of Demag axial & GHH Bull Gear compressor and low balancing rotor	Germany	University
December 2013	Troubleshooting and replacement of a control valve spindle Siemens SST-600 25 Mw	Sweden	Power plant
December 2013	Inspection and cleaning intake filter Steam Turbine Alsthom Rateau Soget typ 9100 CP 43 9 MW	France	Chemical plant
November 2013	Intervention Steam Turbine Alsthom Rateau Soget typ 9100 CP43 9MW	France	Chemical plant
November 2013	Alignment check Blohm&Voss steam turbine MAN	Sweden	Power plant
November 2013	Assisting a gearbox installation Blohm&Voss Marc 4 H-04 15 Mw	Sweden	Power plant
October 2013	Balancing of a rotor steam turbine Worthington R2R	The Netherlands	Refinery
October 2013	Delivery of parts and assembly of turbocompressor Sulzer Esser Wyss RT28	Switzerland	Power plant
October 2013	Overhaul of steamturbine KKK AFA4 G3a Siemens	Germany	Recycling plant
October 2013	Inspection of rotor and upper casing Blohm&Voss KR40/50-2 2,7MW	Germany	Waste plant
October 2013	Inspection of gearbox and steamturbine AEG Kanis Siemens 13 MW	Netherlands	Activated carbon plant
October 2013	Major overhaul and rotor interstage seal repair of a Siemens STT-300 28Mw turbine	Sweden	Paper Mill

October 2013	Installation of shaft seals Stal DM65 17,2 MW Siemens	Sweden	Bio refinery
September 2013	Delivery and installation of turbine starter for a Allison KB501 gas turbine RR	The Netherlands	Paper mill
September 2013	Minor overhaul Steam Turbine Tuthill Nadrowski Dresser-Rand B7ES-4 3MW	France	Waste plant
September 2013	Inspection Turbo Compressor Brown Boveri - Escher Wyss 90/4a EK	Switzerland	Salt mine
September 2013	Major overhaul of a STAL DDM 2070 30 Mw steam turbine	Sweden	Pulp mill
September 2013	Configuration turbine Tuthill Nadrowski Dresser Rand B5S4 2,7 MW	France	Waste plant
September 2013	Inspection C2001 compressor Sulzer	Norway	Bio refinery
September 2013	Intervention Allison KB501 gasturbine RR	The Netherlands	Food Industry
August 2013	Inspection Woodward governor and actuator of a 1-stage Worthington	The Netherlands	Refinery
August 2013	Delivery reconditioned governor valve assembly for Terry 24 ZSA-1 steam turbine	Germany	Refinery
August 2013	Delivery and installation combustion liners Allison 501KB gasturbine RR	Denmark	Power plant
August 2013	Inspection Taiko (BP/HP) pump	France	Metallurgic industry
August 2013	Installation of electronic speed pickup Siemens SST-600 25MW	Sweden	Power plant
August 2013	Supervision during steam systems tests ABB/ACEC 6,2MW turbine Siemens	Sweden	Chemical plant
July 2013	Minor overhaul of ABB VAX 24MW tandem turbine Siemens	Sweden	Power plant
July 2013	Inspection and repair of control valves Siemens ABB VA25-ATP 11MW	Sweden	Power plant
July 2013	Repair and installing of new valve parts for Blohm+Voss Marc 4-H04 15,9 MW turbine	Sweden	Power plant
July 2013	Inspection Elliot 2EPG4-Model E steamturbine	France	Chemical plant
July 2013	Installation new nozzles GTA Alsthom TM2 4 MW	France	Waste plant
July 2013	Inspection turbine control system AEG Kanis steamturbine Siemens	The Netherlands	Activated carbon plant
July 2013	Repair Centrax KB5 gasturbine package	The Netherlands	Food industry
June 2013	Major inspection of generator Blohm+Voss Marc 4 (Alsthom)	Sweden	Power plant
June 2013	Inspection and delivery of spare parts to a Siemens SST-600 25 MW Siemens	Sweden	Power plant
June 2013	Electrical equipment check Siemens SST-110 4 MW Twin turbine	Sweden	Paper mill
June 2013	Safety test of a Blohm+Voss Marc 4	Sweden	Power plant
June 2013	Annual inspection Allison 501 KB gasturbine RR	Denmark	power plant
June 2013	Inspection Alsthom Rateau steamturbine	France	Chemical plant
June 2013	Repair work of STAL DM65 1956 turbine incl. turbine wheel Siemens	Sweden	Bio refinery
Mai 2013	Service of a Voith bull gear compressor	Sweden	Chemical plant
Mai 2013	Boroscope inspection Allison KB5 gasturbine RR	The Netherlands	Paper mill
Mai 2013	Intervention AEG Kanis steamturbine Siemens	The Netherlands	Activated carbon plant
Mai 2013	Minor overhaul Tuthill Nadrowski Dresser rand	France	Waste plant
Mai 2013	Intervention and measuring nozzles GTA TM2 Alsthom	France	Waste plant
Mai 2013	Start up KKK CF4G steamturbine Siemens	France	Chemical plant
Mai 2013	Delivery and installation combustion liners Allison 501KB gasturbine RR	Denmark	Power plant
April 2013	Safety & Functionality tests Siemens SST-600 25 MW	Sweden	Power plant
April 2013	Intermediate inspection Siemens STT 600	The Netherlands	Biomass
April 2013	Inspection and repair of KKK CF4G steam turbine Siemens	France	Chemical plant

April 2013	Minor overhaul Nadrowski turbo-generator Dresser Rand	France	Waste plant
April 2013	Repair work of a AEG-Kanis GE20 2MW turbine Siemens	Sweden	Waste plant
March 2013	Repair work of a ABB/ACEC 6,2 MW turbine Siemens	Sweden	Chemical plant
March 2013	20000 hrs overhaul of a Siemens STT 110 + delivery spare parts Siemens	Germany	Power plant
March 2013	NSC of a Siemens STT 110 Siemens	Germany	Power plant
March 2013	Overhaul DEMAG VK10 compressor Siemens	Germany	Chemical plant
March 2013	Intermediate inspection Centrax KB5 gasturbine package RR	Netherlands	Food industry
March 2013	Delivery complete new controls system Siemens steamturbine TP 2002A	Denmark	Power plant
March 2013	Overhaul Siemens Hydraulic Trip Block HB96611-002A	Denmark	Power plant
March 2013	NSC of a Siemens SST-300 28 MW turbine	Sweden	Paper mill
March 2013	NSC of a Siemens VA25-ATP1 11 MW	Sweden	Power plant
March 2013	NSC of a ABB / ACEC 6,2 MW turbine Siemens	Sweden	Chemical plant
February 2013	NSC of a AEG-Kanis 2MW turbine and Blohm+Voss 9 MW turbine	Sweden	Waste plant
February 2013	Delivery spare parts for KKK CF4G Siemens	France	Chemical plant
February 2013	Activities on Mitsubishi gas turbine MF111B	Italy	Paper mill
January 2013	Safety & Functionality tests Siemens SST-600 36 MW	The Netherlands	Biomass
January 2013	Delivery Spare parts + intervention Coppus RLHA24 Steam turbine	Germany	Pharmaceutical Plant
January 2013	8000 hrs inspection Allison 501 KB gasturbine RR	Denmark	Power plant
January 2013	Rotor inspection Clark 3MX 5/03 K1241	Italy	Chemical plant
January 2013	Trouble shooting and repair work of STAL DM65 Siemens	Sweden	Chemical plant
December 2012	Revamp and control upgrade of KKK CF4G Siemens	France	Chemical plant
November 2012	Feasibility study Maintenance cycle SST 600 Siemens 36 Mw	The Netherlands	Biomass
October 2012	Intervention Dresser Rand Tuthill Nadrowski 2,7 Mw typ B5S4 control & Island mode	France	Incineration
October 2012	Overhaul ABB Fläkt Turbo HAXRG 80/1938	Norway	Paper mill
September 2012	Overhaul of STAL DM65 17250 Kw Siemens	Sweden	Chem/power plant
August 2012	Overhaul of turbo compressor BBC/Sulzer Typ VWR 565	Swiss	Salt factory.
August 2012	Overhaul of integral geared Radial turbo compressor Gec Alsthom C01 typ SM55-45-30	Swiss	Air separation
July 2012	Safety test of a Blohm+Voss Marc 4-HO4 15,9 MW	Sweden	Power plant
July 2012	Major overhaul Siemens SST 060 2,5 Mw.	Sweden	Chemical plant.
July 2012	Revision and adaption oil system Worthington R2R	The Netherlands	Refinery
July 2012	Exchange of Solar Taurus 60 Gas Turbine , Turbomach package.	Germany	Pharma industry
July 2012	Exchange of Solar GT Gas Turbine , Turbomach package.	Germany	Power
June 2012	Major Inspection turbine Siemens SST 600. 25 Mw.	Sweden	Power
June 2012	Disassembly of Gas Turbine Solar Taurus 7301, Turbomach package.	Germany	Power plant
Mai 2012	Inspection of steam turbine Acec 13 Mw.Condense turbine Siemens	Belgium	Chemical plant
Mai 2012	Overhaul of KKK BF4/50 Steam Turbine Siemens	Germany	Chemical plant
Mai 2012	Overhaul of Turbocompressor Alsthom Rateau C01	Switzerland	Air separation industry
Mai 2012	Inspection of STAL DM65 Siemens	Sweden	Chemical plant

Mai 2012	Inspection of generator 501 Centrax Turbine	Denmark	Power plant
Mai 2012	Inspection of 2 Stal Turbines DDM2070/DCDUM2070 Siemens	Sweden	Power
Mai 2012	Repair of 2 x pumps Taiko + 2 x compr. Kwangshin	France	Chemical plant
Mai 2012	Overhaul SST 600 Siemens turbine . 25 Mw.	Sweden	Power
April 2012	Overhaul of turbocompressor SULZER BBC 90/4a EK	Switzerland	Salt plant
March 2012	Minor overhaul of KKK 4.243 MW SST 110 Twin Steam Turbine	Sweden	Paper plant
March 2012	Overhaul of Steam Turbine KKK-K5B and boiler feed pump Siemens	Sweden	Power
March 2012	Check of safety functionalities of a Blohm & Voss 9 Mw. Steam Turbine	Sweden	Power plant
March 2012	Inspection of bearings GHH Verdichter	Germany	Automotive
March 2012	Overhaul KKK AF 3.5G Steam turbine Siemens	Germany	Chemical
March 2012	First Inspection Siemens KKK AF4/G6A 1.6 turbine Siemens	Germany	Paper mill
March 2012	Inspection Ingersoll-Rand Centac C80MXS	UK	Power plant
March 2012	Overhaul Rest gas-turbine M.A.N. 5280 GTG 6/80	Germany	Chemical
March 2012	Inspection of gearbox Rolls Royce Allison 501KB5	The Netherlands	Paper Mill
March 2012	Troubleshooting gas turbine Rolls Royce Allison 501KB5	Denmark	Incineration
March 2012	Inspection of SST 600 25 MW Siemens turbine	Sweden	Incineration
March 2012	Overhaul boiler feed pump Worthington 3UYD10	France	Automotive
February 2012	Inspection of gas turbine Solar Taurus 5 Mw.,Turbomach package.	Germany	Automotive
January 2012	Major overhaul of steam turbine & generator set CEM typ DG SS28p/6500 kW	France	Chemical Plant
January 2012	Major overhaul of Alsthom steam turbine Soget type 9100CP43 and generator– 9 MW	France	Chemical Plant
December 2011	Troubleshooting & service of AEG Kanis G16 1 MW steam turbine Siemens	Germany	Food Industry
December 2011	Overhaul of turbo compressor BBC Turbo 111-4AEK Sulzer	Switzerland	Chemical Plant
December 2011	Inspection of integrally geared centrifugal compressor Alsthom SM55-45	Switzerland	Chemical Plant
November 2011	Major overhaul of integral geared compressor Demag VK 10 Siemens	Germany	Chemical Plant
November 2011	Overhaul of multistage steam turbine AEG Kanis G16 3,5 MW Siemens	Germany	Food Industry
November 2011	Inspection of inline centrifugal compressor Clarj 4M9-6 & 2M10-8 3,6 MW – 2,9 MW	Serbia	Chemical Plant
October 2011	Troubleshooting & service of BBC 3 MW back-pressure steam turbine generator	Belgium	Chemical Plant
October 2011	Installation of steam turbine controls & hydraulic system upgrade 10 MW AEG	The Netherlands	Chemical Plant
September 2011	Inspection of gas turbine Solar Taurus 60 control system 5 MW	Belgium	Paper Mill
September 2011	Inspection RWT Gearbox of 2 MW Dresser Rand steam turbine	Belgium	Chemical Plant
August 2011	Troubleshooting Chlorine turbo compressor PGW Siemens	The Netherlands	Chemical/Salt Plant
August 2011	Major overhaul of 10 MW AEG steam turbine,generator, partial re-blading of rotor	The Netherlands	Chemical Plant
July 2011	Overhaul of turbo compressor comp 4, Volko 4 nr 4530	Germany	Automotive
July 2011	Overhaul & repair IGV of integral geared Radial turbo compressor Alsthom C01	Switzerland	Air Separation
June 2011	Overhaul of 2 turbo compressors BBC/Sulzer Typ VWR 565	Switzerland	Salt Factory
Mai 2011	Major overhaul of a Peter Brotherhood steam turbine 5175 kW	Sweden	Biomass
April 2011	Major overhaul of Atlas Copco integral geared Air compressor HLR 8 – 3.8	Belgium	Air Separation
March 2011	Repair of a Worthington S2SHA turbine rotor	France	Automotive

January 2011	Supply & installation of new hot gas section of Rolls Royce Allison 501KB5	The Netherlands	Paper Mill
October 2010	Overhaul multistage centrifugal Pump Worthington 3UYD 10-11 SS	France	Automotive
October 2010	Overhaul of 3 stages centrifugal compressor Dresser Rand 1M3 428 kW	Hungary	Refinery
September 2010	Overhaul 6 stages centrifugal compressor Dresser Rand 2M10-6 MSC 3300 kW	Hungary	Refinery
September 2010	Repair of 7 stages centrifugal compressor Elliott 38M9I S/N L8060R1 10652 HP	Hungary	Refinery
August 2010	Overhaul of gas expander MAN Turbo E56-3V 8345 kW	Czech Republic	Chemical Plant
August 2010	Overhaul of centrifugal turbo compressor MAN Turbo RIK 100-5 410 kW	Czech Republic	Chemical Plant
July 2010	Overhaul of centrifugal turbo compressor Kobe Steel VG73 850 Kw	Czech Republic	Chemical Plant
June 2010	Overhaul of steam turbine Siemens G300 V5 3300kw	Germany	Chemical Plant
Mai 2010	LTSA for Rolls Royce Allison KB501 RR	Denmark	Incineration
Mai 2010	Delivery & installation of controls on a 4MW ACEC Steam turbine Siemens	Belgium	Chemical Plant
February 2010	Upgrade of Gas turbine Rolls Royce Allison 501KB5 controls to SIL2 level	Germany	Paper Mill
January 2010	Major overhaul of Rolls Royce Allison 501KB5 Gas turbine	Denmark	Biomass
January 2010	Delivery & installation of a 1.5 MW AEG steam turbine & generator controls	Belgium	Chemical Plant
December 2009	Overhaul in-line centrifugal compressor Delaval Stork 8BK22	Italy	Refinery
November 2009	Overhaul in-line centrifugal compressor & steam turbine Nuovo Pignone	Italy	Refinery
October 2009	Overhaul integrally geared centrifugal compressor Demag VK32 Siemens	Slovakia	Refinery
September 2009	Overhaul of axial compressor Sulzer AC-14 (16)-32 3100kW	Germany	Chemical Plant
August 2009	Supply & installation of a Rolls Royce Allison 501KB5 generator controls	Turkey	Paper Mill
July 2009	Overhaul of in-line centrifugal compressor Brown Boveri VWR 565 3400 kW	Switzerland	Pharmaceutical Plant
July 2009	Delivery & installation of a 4.8 MW Acec steam turbine generator controls Siemens.	Belgium	Incineration plant
June 2009	Overhaul of Axial Blower Nuovo Pignone/Boldrocchi AF112-11 Axial Fan	Norway	Refinery
Mai 2009	Overhaul of In-line Centrifugal compressor Delaval Stork C2C26 – FSMVSFNC5R	Sicily	Refinery
April 2009	Overhaul of In-line Centrifugal compressor Nuovo Pignone BCL 304	Sicily	Refinery
March 2009	Relocation of 2 5.2 MW Solar Taurus gas turbine & generator controls , Turbomach	India	Paper Mill
February 2009	Supply & installation controls on a 5.2 MW gas turbine Solar Taurus.Turbomach	The Netherlands	Paper Mill
November 2008	Supply & installation of a 3.6 MW gas turbine Rolls Royce Allison KB5 control system	Turkey	Paper Mill
September 2008	Exchange of gas turbine Rolls Royce Allison KB5 Compressor section	Denmark	Incineration
August 2008	Inspection of gas turbine compressor section Rolls Royce KB5	The Netherlands	Subcontracting
July 2008	Supply & installation of a gas turbine Solar Centaur	Germany	Paper Mill
April 2008	Supply of 3.6 MW gas turbine Rolls Royce controls	The Netherlands	Paper Mill
January 2008	Inspection & exchange of a Rolls Royce Allison KB5	The Netherlands	Paper Mill
August 2007	Supply & installation of a 3.6 MW Solar Centaur gas turbine control system Turbomach	The Netherlands	Paper Mill
March 2007	Installation of 5.2 MW Solar Taurus Low nox gas turbine controls Turbomach Package	Germany	Chemical Plant